

Utah's Summary Information On Underground Storage Tanks (USTs)

General Information

Public Record Posted Date: 10/2/2008

Total Number Of UST Facilities: 1467

Total Number Of USTs: 4017

Summary Information For On-Site Inspections

Number of UST Facilities Inspected: 1240

Inspection Period Dates: October 1, 2007 To September 30, 2008

Percent Compliance at Time of Inspection (Combined Measure): 60%

Note: Tank, facility, and on-site inspection information is based on State of Utah site inspections, and file records. On-site inspections measure compliance with State and Federal UST regulations. Percent Compliance is based on the combined performance measure (release detection and release prevention compliance) of the significant operational compliance (SOC) requirements described in EPA's September 30, 2003 Memorandum.

Summary Information For Releases

Number Of Confirmed UST Releases: 37

Release Reporting Period Dates: October 1, 2007 To September 30, 2008

Summary Information For Release Sources And Causes

Source			Cause													
			Spill		Overfill		Damage		Corrosion		Install		Other		Unknown	
	#	%	#	%	#	%	#	%	#	%	#	%	#	%	#	%
Tank	15	41%	1	25%	6	86%	1	20%	2	100%	0	0%	1	33%	4	29%
Piping	7	19%	1	25%	0	0%	3	60%	0	0%	0	0%	0	0%	2	14%
Dispenser	7	19%	1	25%	0	0%	1	20%	0	0%	1	100%	2	67%	2	14%
Submersible Turbine Pump	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%
Delivery Problem	1	3%	1	25%	0	0%	0	0%	0	0%	0	0%	0	0%	0	0%
Other	7	19%	0	0%	1	14%	0	0%	0	0%	0	0%	0	0%	6	43%
Totals	37	100%	4	100%	7	100%	5	100%	2	100%	1	100%	3	100%	14	100%

= number, % = percent of total number

Note: Release, source and cause information is based on Federally Regulated Underground Storage Tanks and Federally Regulated Leaking Underground Storage Tanks. Source and cause data were collected using data provided to the State of Utah from Site Inspections and Closure Notices.